



Contractors License 544530
 P.O. Box 591-I, Healdsburg, CA 95448-0590
 1-888-UNPLUGU • (707) 433-8053 • FAX(707) 433-8085
 www.unplugu.com

Sewer Lateral Inspection



To confirm the success of the drilling operation, MSI's sewer lateral inspection units inspect the sewer mains and laterals providing video to verify the condition of the pipe after construction is complete. The inspection of the sewer main and the lateral connections is conducted from the manhole causing no more inconvenience to area residents than a standard video inspection.

A picture-in-picture format allows visuals from both cameras simultaneously allowing the operator to investigate both the sewer main and the sewer laterals.



The launch system camera can be remotely rotated by the operator for easy insertion into the lateral with a range of up to 100'. Assessments regarding the condition of the sewer lateral are compliant with NASSCO LACP.

